

6.5. HWA-M4: System Not Appropriately Hardened

The embedded operating system was not suitably hardened to attack. This included having no security policies on the binaries and leaving unnecessary binaries and functionality on the system.

It is recommended that all unnecessary binaries are removed from the device and security properties are applied where possible.

Medium Risk
CVSS 4.4

Description

The device was found to be insufficiently hardened against attack. This was discovered in two key areas.

Firstly,

[Redacted]

[Redacted]

Secondly, the key binaries in use, including the ones that have the ability to handle all input and output on the device, did not use the “NX” flag, stack canaries, or fortified function compiler flags. These all make it much harder to exploit issues such as buffer overflows.

```
(kali@kali)-[~]
└─$ /opt/checksec.sh-2.6.0/./checksec --dir=./files/
RELRO      STACK CANARY      NX      PIE      RPATH      RUNPATH      Symbols      FORTIFY Fortified      Fortifiable      Filename
Partial RELRO  No canary found  NX enabled  No PIE    No RPATH    No RUNPATH    No Symbols    No      0                10               ./files/balena-engine
Partial RELRO  No canary found  NX enabled  No PIE    No RPATH    No RUNPATH    No Symbols    No      0                0                ./files/balena-engine-init
```

Figure 11: CheckSec running against binaries



Recommendations



Binaries should be compiled with appropriate compile-time hardening enabled.

Affected	
References & CVSSv3 Metrics	Root Cause: Implementation Base Metrics: AV:A/AC:L/PR:L/UI:N/S:U/C:L/I:L/A:N (4.6) Temporal Metrics: E:H/RL:O/RC:C (4.4) Environmental Metrics: CR:M/IR:M/AR:M (4.4)